

SBT ScannerTool 102

Quick Start Guide

Start Up (Internet Connection is Required)

1) Load USB drivers by entering the following url in you web browser (it is case sensitive):

<http://shopsbt.com/SBTTool/Install/Driver/USBDriver.exe> and hit "Run"

2) Connect your SBT ScannerTool 102 to your computer with the USB cable

3) Install SBT ScannerTool 102 software by entering the following url (it is case sensitive)::

<http://www.shopsbt.com/SBTTool/Install/SBTSetup.msi> and hit "Run"

4) Start the program by:

Click on Start in the lower left of your screen

Click on "All Programs"

Move your mouse over "SBT Products", then click on SBT Diagnostic 102"

Click on "Activate Scan Tool"

Call SBT (727-443-0373) with the serial number.

You will be given 2 keys to activate.

After the first connection

1) Connect the SBT ScannerTool 102 to the computer with the USB cable

2) Start SBT Diagnostic 102 through the Start menu

Vehicle Connection

There are two ways to connect the PWC after you have opened the program:

1) For 4-TEC and DI (and 2005 RFI):

- Use the 9-pin to 6-pin cable and connect the ScannerTool 102 to the diagnostic port on the ski

- Lanyard must be on the DESS post to power up the ECU

2) For 2-Stroke DESS and RFI

- Connect the Post adapter cable to the ScannerTool 102

3) After connecting the cable, go to the "Vehicle" drop down in the upper left and drag down to "Read Vehicle".

Additional questions can be answered by using the "Help" pull down, "Help" category, "Getting Started"