

2011 SBT Replacement Core Charges*

This list is provided as a guideline to our customers for items that are often damaged or missing from their core.
Additional charges may apply not listed below, such as missing bolts and other items specific to certain engines.

Sea-Doo					
Engine	Case	Cylinder	Crankshaft	Head	Head Cover
587	\$150.	\$25. ea	\$200.	\$20.	\$30.
657/657X	\$150.	\$25. ea	\$200.	\$20.	\$30.
717	\$799.	\$400. ea	\$250.	\$200.	\$90.
787/787 RFI	\$850.	\$400. ea	\$250.	\$200.	\$95.
951	\$875.	\$690.	\$250.	\$290.	
951 DI	\$1155.	\$850.	\$250.	\$440.	

R.A.V.E Valves	\$150. ea	Crank Gears	\$75.00
Counter Balance Shaft	\$200.	Counter Balance Gears	\$75.00
Rotary Cover	\$100.		

Kawasaki					
Engine	Case	Cylinder	Crankshaft	Head	Head Cover
440	\$340.	\$400.	\$200.	\$150.	
550	\$400.	\$600.	\$250.	\$140.	
650	\$150.	\$195.	\$250.	\$50.	
750 (All)	\$200.	\$300.	\$250.	\$70.	
900	\$475.	\$750.	\$300.	\$290.	
1100	\$500.	\$800.	\$300.	\$300.	
1100 DI	\$590.	\$800.	\$300.	\$350.	
1200	\$550.	\$450. ea	\$300.	\$110. ea	
4 Strokes	Cylinder Block	Cylinder Head	Spun Bearing		
12F & 15F	\$995.	\$400.	\$200. ea		

Polaris					
Engine	Case	Cylinder	Crankshaft	Head	Dome Covers
650/750	\$150.	\$100. ea	\$250.	\$25. ea	
700	\$375.	\$400. ea	\$250.	\$75. ea	\$40. ea
777	\$750.	\$350. ea	\$300.	\$75. ea	\$40. ea
800 DI	\$750.	\$350. ea	\$300.	\$75. ea	\$40. ea
780	\$150.	\$100. ea	\$250.	\$25. ea	
900	\$750.	\$300. ea	\$250.	\$75. ea	\$40. ea
1050	\$750.	\$300. ea	\$250.	\$75. ea	\$40. ea
1200 Carb	\$750.	\$300. ea	\$300.	\$75. ea	\$40. ea PTO Head
1200 DI	\$750.	\$500. ea	\$300.	\$175. ea	\$125. ea

* Replacement Core Charges apply to any component received by SBT that is missing, modified, or damaged beyond reasonable repair.

2011 SBT Replacement Core Charges*

This list is provided as a guideline to our customers for items that are often damaged or missing from their core. Additional charges may apply not listed below, such as missing bolts and other items specific to certain engines.

Yamaha					
Engine	Case	Cylinder	Crankshaft	Head	Head Cover
500	\$595.		\$250.	\$100.	
650	\$150.	\$150.	\$250.	\$50.	
701X	\$150.	\$150.	\$250.	\$50.	
701 S&T	\$150.	\$150.	\$250.	\$50.	
760	\$600.	\$495.	\$250.	\$200.	
800	\$550.	\$650. ea	\$250.	\$250.	
1100	\$850.	\$750.	\$300.	\$200.	\$100.
1200	\$600.	\$800.	\$300.	\$200.	\$100.
1200 PV	\$800.	\$595. ea	\$300.	\$250.	
1300 PV	\$800.	\$595. ea	\$300.	\$250.	
Power Valves	\$59.95 ea				

Tigershark					
Engine	Case	Cylinder	Crankshaft	Head	
640	\$515.	\$555.	\$200.	\$175.	
770	\$770.	\$675.	\$200.	\$195.	
900	\$970.	\$315. ea	\$200.	\$80. ea	
1000	\$945.	\$315. ea	\$200.	\$80. ea	

All 4 Strokes				
Engine	Cylinder Block	Cylinder Head	Spun Bearing	
All 4 Tec	\$995.	\$400.	\$200. ea	
12F&15F	\$995.	\$400.	\$200 ea	
F12/R12 & X	\$995.	\$400.	\$200. ea	

* Replacement Core Charges apply to any component received by SBT that is missing, modified, or damaged beyond reasonable repair.